IN THE DRAWINGS

The attached drawing sheet includes a change to Figure 4. The sheet which includes Figure 4 replaces the original sheet including Figure 4. The figure has been amended to extend the line 463 to the right to intersect the switches in sub-network 420. It is respectfully submitted that the proposed amendment to the drawing does not add new matter.

Attachment:

Replacement Sheet

Annotated Sheet Showing Change

REMARKS

This application has been allowed. Applicants respectfully request, however, that the Examiner additionally enter this Amendment Under 37 C.F.R. § 1.312(a) to correct for typographical errors.

In particular, paragraph 0034 has been amended to correct typographical errors. Support for the amendments in paragraph 0034 may be found in Figure 3. In Figure 3, the upper two input conductors 101-102 are associated with conductors 306-310 (B0-B4) of network 320 which is referred to as Mb.

Figure 4 has been amended to correct for an error by extending line 463 to the right to intersect the switches of 420. Support for the amendment of Figure 4 may be found in the paragraphs 0037 and 0038 which describe that line 463 connects to conductors 112 and 116 through switches in sub-network 420.

If the Examiner believes a telephone interview would expedite the prosecution of this application, the Examiner is invited to contact Daniel Ovanezian at (408) 720-8300.

If there are any additional charges, please charge our Deposit Account No. 02-2666.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP

Dated: 7/7, 2005

Daniel E. Ovanezian Registration No. 41,236

12400 Wilshire Boulevard Seventh Floor Los Angeles, CA 90025-1026 (408) 720-8300




FIG. 4